Division of Health Care Facilities (X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: 01 - MAIN BUILDING 01 A. BUILDING B. WING 11/28/2011 TN1401 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 120 PITCOCK LANE CELINA HEALTH AND REHABILITATION CENT CELINA, TN 38551 (X5) COMPLETE PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X4) ID ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** CROSS-REFERENCED TO THE APPROPRIATE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) N 002 1200-8-6 No Deficiencies N 002 Based on observation, testing, and records review, it was determined that the facility did not have any life safety deficiencies. Division of Health Care Facilities (X6) DATE TITLE Caul Boone LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE If continuation sheet 1 of 1 STATE FORM QSDD21